## Tohoku Journal of Natural Disaster Science

## Volume 59

## March, 2023

ARTICLES	Page
Mechanical Study of Triggered Earthquakes Caused by the 2011 Tohoku-Oki Earthquake Daichi WATANABE et al. Strong Motion Records Observed in Buildings During 2019-2022 Earthquakes in Tohoku Region	1
	7
Depth Estimate Using P-wave Later Phase from Pacific Offshore Earthquakes of Tohoku District Masahiro KOSUGA	13
The 1983 Hokkaido-Nansei-Oki Earthquake for Aomori Prefecture Hiroshi KAGAMI and Toshihiko MIZUTA	19
CMT Inversion for Earthquakes in and Around Aomori Prefecture, Northern Honshu, Japan,	
Using Three-Dimensional Heterogeneous Velocity Structure	25
Study on Impact Force of Tsunami Drifting Objects Using Load Cells	
	31
Characteristics of Event Deposits in Sekine-hama, Shimokita Peninsula Yuta KIMURA, Rina OKADA and Koji UMEDA	37
Research on Tsunami Evacuation Considering Regional Conditions Based on Evacuation Behavior Analysis	
Shin-ya HORIAI, Ikumi TACHIHANA, Kanta ENDO, Shinsuke TAKASE, Masaya KATO and Yasushi TAKEYAMA Hydraulic Model Tests of Tsunami Force Acting on Oil Tanks	41
	45
Froude Number and Drag Coefficient in the Evaluation of Drag Force Due to a Tsunami Inundation Flow	10
	51
Fundamental Study of Fluid Forces Acting on Structures	
Ikumi TACHIHANA, Kanta ENDO, Shinya HORIAI, Shinsuke TAKASE and Masaya KATO	57
Study of the Influence of Vegetation and Driftwood in the River Channel	
Soshi OMORI, Yoshitaka JIKEN, Noritoshi SAITO and Kazuya WATANABE	63
Study on the Behavior of the Sandbar Using UAV and Riverbed Fluctuations in Babame River 	69
Hydraulic Experiment on the Bark Peeling of Driftwood Generated by Heavy Rainfall	
	75
Report on Survey of Flood Damage of August 2022 in Ichinohe Town Yuriko MATSUBAYASHI and Norihiko KONNO	81
Damage Caused by the Flood Generated to Heavy Rain at Northern Tohoku Region in Augast 2022	
Kazuya WATANABE and Yuriko MATSUBAYASHI	87
Investigation and Research on Downpour Disaster in August, 2022 in Aomori Prefecture	
Mikio SASAKI, Takahiro TAKEUCHI, Shinsuke TAKASE and Yuta MITOBE	93
Development of Seismic and Tsunami Measure Technology by Using Cushioning Materials Yoshiaki ARIGA	99
A Fundamental Study on Collapsed Carports During Snowy Earthquake Shunichi KATAOKA and Erina KISHI	105
Vibration Response Characteristics of Multi Story Frame Attached with Liquid Damper Kodai MIZUMA et al.	111
Vibration Response Characteristics of Multi Story Frame Attached with Liquid Damper KKentarou KOJIMA et al.	117
Seismic Response of a Building Composed of Several Blocks of Different Construction Ages	
Tomoki MIZUNO and Shunichi KATAOKA	123
Stresses Acting on the Roof Bearing of Gymnasium Structure Subjected to Earthquake Motion in two Directions	
Sayaka ABE, Tomomi FUJITA, Naoki FUNAKI and Masayuki HANDOU	129
Evacuation Drill at a Visitor Facility and its Consideration from the Perspective of Tourism Risk/Crisis Management	
	135
$\label{eq:constructure} Age \ Structure \ of \ Post-Disaster \ Inter-Prefectural \ Migration \ \dots \ Makoto \ OKUMURA \ and \ Hatsune \ MOTOI$	141
Tracking of the 1983 Nihonkai-Chubu Earthquake Disaster by Newspaper Articles	
Toshihiko MIZUTA and Hiroshi KAGAMI	145

## Tohoku Research Group for Natural Disaster Science